


P03-GDF-716

Machine: TSUGAMI

Type: P03

Emplacement, N°: T01+T02 / T13+T14 / T14+T15 / T15+T16 / T16+T17

Travail sur: Broche principale / Broche de reprise


Type de travail: n_{max}: - [rpm]i (n_i / n_o): -

Attachement: Autre

Sans refroidissement

Infos:

- Porte-barre d'alésage
- 5xØ16

P03-GDF-716


Machine: TSUGAMI

Type: P03

Location, N°: T01+T02 / T13+T14 / T14+T15 / T15+T16 / T16+T17

Work on: Main spindle / Back spindle

Type of work: 

n_{max} : - [rpm]


i (n_i / n_o): 1 / 1

Attachement: Other

Without coolan Maximum pressure: _ [bar]

Infos:

- Boring bar holder
- 5xØ16

P03-GDF-716

Machine: TSUGAMI

Typ: P03

Position, N°: T01+T02 / T13+T14 / T14+T15 / T15+T16 / T16+T17

Arbeit über: Hauptspindel / Abgreifspindel


Arbeitstyp: n_{max}: - [rpm]i (n_i / n₀): -

Befestigung: Andere

Ohne Kühlmittel

Infos:

- Bohrstangenaufnahme
- 5xØ16

P03-GDF-716

Macchina: TSUGAMI

Tipo: P03

Posizione, N°: T01+T02 / T13+T14 / T14+T15 / T15+T16 / T16+T17

Lavoro al: Mandrino principale / Contromandrino

Tipo di lavoro: n_{max}: - [rpm]i (n_i / n₀): -

Ataccamento: Altro

Senza refrigerante

Informazioni:

- Porta-barra di alesaggio
- 5xØ16