


P03-GDF-416



Machine: TSUGAMI

Type: P03

Emplacement, N°: T11+T12 / T12+13 / T13+T14 / T14+T15

Travail sur: Broche principale / Broche de reprise

Type de travail:  

n_{max} : - [rpm]


i (n_i / n_o): 1 / 1

Attachement: Autre

Sans refroidissement Pression maximale: _ [bar]

Infos: Porte-barre d'alésage 3xØ16

P03-GDF-416



Machine: TSUGAMI

Type: P03

Location, N°: T11+T12 / T12+13 / T13+T14 / T14+T15

Work on: Main spindle / Back spindle

Type of work:  

n_{max} : - [rpm]


i (n_i / n_o): 1 / 1

Attachement: Other

Without coolan Maximum pressure: _ [bar]

Infos: Boring bar holder 3xØ16

P03-GDF-416




Maschine: TSUGAMI

Typ: P03

Position, N°: T11+T12 / T12+13 / T13+T14 / T14+T15

Arbeit über: Hauptspindel / Abgreifspindel

Arbeitstyp: 

n_{max} : - [rpm]


i (n_i / n_o): 1 / 1

Befestigung: Andere

Ohne Kühlmittel Drück: _ [bar]

Infos: Bohrstangenaufnahme 3xØ16

P03-GDF-416




Macchina: TSUGAMI

Tipo: P03

Posizione, N°: T11+T12 / T12+13 / T13+T14 / T14+T15

Lavoro al: Mandrino principale / Contromandrino

Tipo di lavoro: 

n_{max} : - [rpm]

$i (n_i / n_o)$: 1 / 1

Ataccamento: Altro

Senza refrigerante Pressione massima: _ [bar]

Informazioni: Porta-barra di alesaggio 3xØ16