


1000-SC020-RA0000-1S02

Machine: HANWHA

Type: XD38

Emplacement, N°: Upper gang tool post


Travail sur: Broche principale

Type de travail: i (n_i / n_o): 1 / 1

Attachement: ER20

Sans refroidissement

Infos: Angle ajustable +/-46°
(angle réglable +/-16° & 3 plats sur la queue à -30° / 0° / 30°)

1000-SC020-RA0000-1S02

Machine: HANWHA

Type: XD38

Location, N°: Upper gang tool post

Work on: Main spindle


Type of work: i (n_i / n_o): 1 / 1

Attachement: ER20

Without coolant

Infos: Adjustable angle +/-46

(adjustable angle +/-16° & 3 flats on shank at -30° / 0° / 30°)

1000-SC020-RA0000-1S02

Maschine: HANWHA
Typ: XD38
Position, N°: Upper gang tool post
Arbeit über: Hauptspindel
Arbeitstyp: 
i (n_i / n_o): 1 / 1
Befestigung: ER20

Ohne Kühlmittel

Infos: Einstellbarer Winkel +/-46°.

(Winkel einstellbar +/-16° & 3 Abflachungen am Schaft bei -30° / 0° / 30°.