


0400-HF200-R00000-4S01

Machine: TSUGAMI

Type: P036W

Emplacement, N°: Back gang tool post

Travail sur: Broche principale / Broche de reprise


Type de travail: i (n_i / n_o): -

Attachement: 4x Ø20.0 HF

Sans refroidissement

Infos:

Utilise 2 positions de burins.


0400-HF200-R00000-4S01

Machine: TSUGAMI
Type: P036W
Location, N°: Back gang tool post
Work on: Main spindle / Back spindle
Type of work: 
i (n_i / n_o): -
Attachement: 4x Ø20.0 HF

Without coolant

Infos:

Uses 2 chisel positions.

0400-HF200-R00000-4S01

Machine: TSUGAMI

Typ: P036W

Position, N°: Back gang tool post

Arbeit über: Hauptspindel / Abgreifspindel

Arbeitstyp: i (n_i / n_o): -

Befestigung: 4x Ø20.0 HF

Ohne Kühlmittel

Infos:

2 Schneidepositionen verwenden