


LL-ZBD0-CR-3x

Machine: GOODWAY

Type: SW42

Emplacement, N°: T3300 / T3400

Travail sur: Broche principale


Type de travail:

i (n_i / n_o): 1 / 3

Attachement: ER 11

Sans refroidissement

Infos: Porte-outil entraîné à changement rapide

LL-ZBD0-CR-3x

Machine: GOODWAY

Type: SW42

Location, N°: T3300 / T3400

Work on: Main spindle


Type of work:

i (n_i / n_o): 1 / 3

Attachement: ER 11

Without coolant

Infos: Radial driven toolholder with quick change

LL-ZBD0-CR-3x

Machine: GOODWAY

Typ: SW42

Position, N°: T3300 / T3400

Arbeit über: Hauptspindel


Arbeitstyp:

i (n_i / n_o): 1 / 3

Befestigung: ER 11

Ohne Kühlmittel

Infos: Werkzeughalter Schnellewechsel system

LL-ZBD0-CR-3x

Macchina: GOODWAY

Tipo: SW42

Posizione, N°: T3300 / T3400

Lavoro al: Mandrino principale

Tipo di lavoro:

i (n_i / n_o): 1 / 3

Ataccamento: ER 11

Senza refrigerante

Informazioni: Porta-attrezzo trascinato a cambiamento veloce