


LL-ZBD0-CR-2x

Machine: GOODWAY

Type: SW42

Emplacement, N°: Coulisse linéaire / T3400

Travail sur: Broche principale


Type de travail:  $n_{\max}$: 10'000 [rpm] $i (n_i / n_o)$: 1 / 2

Attachement: ER 11

Sans refroidissement

Infos: Porte-outil entraîné à changement rapide

LL-ZBD0-CR-2x



Machine: GOODWAY

Type: SW42

Location, N°: Gangtool / T3400

Work on: Main spindle

Type of work: 


n_{max} : 10'000 [rpm]

$i (n_i / n_o)$: 1 / 2

Attachement: ER 11

Without coolant

Infos: Radial driven toolholder with quick change

LL-ZBD0-CR-2x

Machine: GOODWAY

Typ: SW42

Position, N°: Vertikalhalter / T3400

Arbeit über: Hauptspindel


Arbeitstyp:  $n_{\max}$: 10'000 [rpm] $i (n_i / n_o)$: 1 / 2

Befestigung: ER 11

Ohne Kühlmittel

Infos: Werkzeughalter Schnellewechsel system

LL-ZBD0-CR-2x



Macchina: GOODWAY

Tipo: SW42

Posizione, N°: Slitta lineare / T3400

Lavoro al: Mandrino principale

Tipo di lavoro: 

n_{max} : 10'000 [rpm]

$i (n_i / n_o)$: 1 / 2

Ataccamento: ER 11

Senza refrigerante

Informazioni: Porta-attrezzo trascinato a cambiamento veloce