


0400-SC011-A00A00-1S01



Machine: TSUGAMI

Type: BW207 – BW208 – BE208Z – BW209Z

Emplacement, N°: T01 - T02 – T11 – T12

Travail sur: Broche principale

Type de travail: 


n_{max} : 30'400 [rpm]

i (n_i / n_o): 1 / 3.8


Attachement: ER 11

Sans refroidissement

Infos:


0400-SC011-A00A00-1S01

Machine: TSUGAMI
Type: BW207 – BW208 – BE208Z – BW209Z
Location, N°: T01 - T02 – T11 – T12
Work on: Main spindle
Type of work: 
 $n_{\max}$: 30'400 [rpm]
 i (n_i / n_o): 1 / 3.8
Attachement: ER 11
Without coolant
Infos:

0400-SC011-A00A00-1S01

Maschine: TSUGAMI
Typ: BW207 – BW208 – BE208Z – BW209Z
Position, N°: T01 - T02 – T11 – T12
Arbeit über: Hauptspindel
Arbeitstyp: 
 n_{max} : 30'400 [rpm]
 i (n_i / n_o): 1 / 3.8
Befestigung: ER 11
Ohne Kühlmittel
Infos:

0400-SC011-A00A00-1S01



Macchina: TSUGAMI

Tipo: BW207 – BW208 – BE208Z – BW209Z

Posizione, N°: T01 - T02 – T11 – T12

Lavoro al: Mandrino principale

Tipo di lavoro: 

n_{max} : 30'400 [rpm]

i (n_i / n_o): 1 / 3.8

Atacco: ER 11

Senza refrigerante

Informazioni: