



**0400-TF080-R00000-9S01**


Machine: TSUGAMI  
Type: P034H / P036W  
Emplacement, N°: Back gang tool post  
Travail sur: Broche principale  
Type de travail:   
i (n<sub>i</sub> / n<sub>o</sub>): -  
Attachement: 9x ■8 mm


Sans refroidissement

Infos:

Attention à la compatibilité des cornes porte-barres d'alésage!

Voir "Table of boring bar holders Tsugami"

**0400-TF080-R00000-9S01**


Machine: TSUGAMI  
Type: P034H / P036W  
Location, N°: Back gang tool post  
Work on: Main spindle  
Type of work:   
i (n<sub>i</sub> / n<sub>0</sub>): -  
Attachement: 9x ■8 mm


Without coolant

Infos:

Pay attention to compatibility of boring bar holders!

See "Table of boring bar holders Tsugami".

**0400-TF080-R00000-9S01**

Maschine: TSUGAMI  
Typ: P034H / P036W  
Position, N°: Back gang tool post  
Arbeit über: Hauptspindel  
Arbeitstyp:   
i (n<sub>i</sub> / n<sub>0</sub>): -  
Befestigung: 9x ■8 mm

Ohne Kühlmittel

Infos:

Achten Sie auf die Kompatibilität der Bohrstangenhalter!

Siehe "Table of boring bar holders Tsugami".