


P03-GDF-616-HF

Machine: TSUGAMI

Type: P03

Emplacement, N°: T01 / T02

Travail sur: Broche principale


Type de travail:  $n_{\max}$: - [rpm] i (n_i / n_o): -

Attachement: -

Sans refroidissement

Infos: Porte-barre d'alésage 2x $\varnothing 16\text{mm}$ (standard) + 1x $\varnothing 19.05\text{mm}$ (HF-cylindrique)

Nakanishi BM319

P03-GDF-616-HF

Machine: TSUGAMI

Type: P03

Location, N°: T01 / T02

Work on: Main spindle

Type of work:


 $n_{\max}$: - [rpm] i (n_i / n_o): -

Attachement: -

Without coolant :

Infos: Boring bar holder 2x $\varnothing 16\text{mm}$ (standard) + 1x $\varnothing 19.05\text{mm}$ (HF-cylindrical)

Nakanishi BM319

P03-GDF-616-HF

Machine: TSUGAMI

Typ: P03

Position, N°: T01 / T02

Arbeit über: Hauptspindel

Arbeitstyp:


n_{max}: - [rpm]i (n_i / n_o): -

Befestigung: -

Ohne Kühlmittel:

Infos: Bohrstangenaufnahme 2xØ16mm (Standard) + 1xØ19.05mm (HF-cylindrisch)

Nakanishi BM319

P03-GDF-616-HF

Macchina: TSUGAMI

Tipo: P03

Posizione, N°: T01 / T02

Lavoro al: Mandrino principale

Tipo di lavoro:  $n_{\max}$: - [rpm] i (n_i / n_o): -

Ataccamento: -

Senza refrigerante

Informazioni: Porta-barra di alesaggio 2x $\varnothing 16\text{mm}$ (standard) + 1x $\varnothing 19.05\text{mm}$ (HF-cilindrico)
Nakanishi BM319