


0400-SC016-A00000-1S06

Machine: TSUGAMI

Type: SS20/32, HS20/32

Emplacement, N°: Back tool post

Travail sur: Broche principale

Type de travail:

i (n_i / n_o): 1 / 1

Attachement: ER16

Sans refroidissement

Infos:

0400-SC016-A00000-1S06**Erreur ! Source du renvoi introuvable.**

Machine: TSUGAMI
Type: SS20/32, HS20/32
Location, N°: Back tool post
Work on: Main spindle
Type of work: 
i (n_i / n₀): 1 / 1
Attachement: ER16
Without coolant
Infos:

0400-SC016-A00000-1S06**Erreur ! Source du renvoi introuvable.**

Maschine: TSUGAMI
Typ: SS20/32, HS20/32
Position, N°: Back tool post
Arbeit über: Hauptspindel
Arbeitstyp: 
i (n_i / n_o): 1 / 1
Befestigung: ER16
Ohne Kühlmittel
Infos: