



LSH-045



Machine: CITIZEN

Type: L12-VII

Emplacement, N°: Coulisse linéaire – T10

Travail sur: Broche principale

Type de travail: 

n_{max} : 10'000 [rpm]

$i (n_i / n_o)$: 1 / 1



Attachement: Arbre Ø4.5mm

Sans refroidissement

Infos:

- Fraise Ø12mm
- Largeur max de fraise : 3...12 mm
- Inclinaison max. 2°

LSH-045



Machine: CITIZEN

Type: L12-VII

Location, N°: Gangtool – T10

Work on: Main spindle

Type of work: 

n_{max} : 10'000 [rpm]

$i (n_i / n_o)$: 1 / 1



Attachement: Shaft Ø4.5mm

Without coolant

Infos:

- Mill Ø12
- Width of mill cutter : 3...12 mm
- Slope max. 2°

LSH-045





Maschine: CITIZEN
 Typ: L12-VII
 Position, N°: Vertikalhalter – T10
 Arbeit über: Hauptspindel
 Arbeitstyp: 
 n_{max} : 10'000 [rpm]
 $i (n_i / n_o)$: 1 / 1
 Befestigung: Schaft Ø4.5mm

Ohne Kühlmittel

Infos:

- Fräser Ø12
- Breite von Fräser: 3...12 mm
- Neigungswinkel Max. 2 °

LSH-045



Macchina: CITIZEN

Tipo: L12-VII

Posizione, N°: Slitta lineare – T10

Lavoro al: Mandrino principale

Tipo di lavoro: 

n_{max} : 10'000 [rpm]

$i (n_i / n_o)$: 1 / 1

Ataccamento: Codolo $\phi 4.5$ mm

Senza refrigerante

Informazioni:

- Frese $\phi 12$
- Larghezza di frese : 3...12 mm
- Inclinazione max. 2°