


**GSE2010**


Machine: CITIZEN

Type: L32-1M8 / L32-1M10 / L32-1M12 / M32-4M5 / M32-4M8 / M32-5M5 / M32-5M7 / M32-5M8

Emplacement, N°: Upper gang tool post

Travail sur: Broche principale


Type de travail:

i (n<sub>i</sub> / n<sub>o</sub>): 1 / 1

Attachement: 2x4xER16

Sans refroidissement

Infos:

**GSE2010**


Machine: CITIZEN

Type: L32-1M8 / L32-1M10 / L32-1M12 / M32-4M5 / M32-4M8 / M32-5M5 / M32-5M7 / M32-5M8

Location, N°: Upper gang tool post

Work on: Main spindle


Type of work:

i (n<sub>i</sub> / n<sub>o</sub>): 1 / 1

Attachement: 2x4xER16

Without coolant

Infos:

**GSE2010**


Machine: CITIZEN

Typ: L32-1M8 / L32-1M10 / L32-1M12 / M32-4M5 / M32-4M8 / M32-5M5 / M32-5M7 / M32-5M8

Position, N°: Upper gang tool post

Arbeit über: Hauptspindel

Arbeitstyp:

i (n<sub>i</sub> / n<sub>o</sub>): 1 / 1

Befestigung: 2x4xER16

Ohne Kühlmittel

Infos: